

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

KR1464
NNW
> 1
1.844 mi.
9738 ft.

BUSINESS - SERVICE STATION
125 KINGS HIGHWAY
BROOKLYN, NY 11207

NY Spills **S123661866**
N/A

Site 3 of 3 in cluster KR

Relative:
Higher

Actual:
20 ft.

SPILLS:

Name: BUSINESS - SERVICE STATION
Address: 125 KINGS HIGHWAY
City,State,Zip: BROOKLYN, NY 11207
Spill Number/Closed Date: 1812287 / Not Reported
Facility ID: 1812287
Facility Type: ER
DER Facility ID: 536670
Site ID: 584254
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2019-03-15
Investigator: RJWHITCH
Referred To: Not reported
Reported to Dept: 2019-03-15
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 1
Date Entered In Computer: 2019-03-15
Spill Record Last Update: 2019-03-22
Spiller Name: TIM FISHER
Spiller Company: UNKNOWN
Spiller Address: 125 KINGS HIGHWAY
Spiller Company: 999
Contact Name: TIM FISHER
DEC Memo: "3/15/2019 - Feng - Duty Desk. Spoke to Tim Fisher of Antea Group. The site property owner is Getty Properties. Their tenant Capital Oil is removing the (4) 4,000-gallon USTs. Island Pump and Tank is the contractor for Capital Oil. Island Pump and Tank has already removed (2) 4,000-gallon USTs in a single cavity, collected endpoint soil samples. The endpoint samples show exceedances of CP-51. The USTs were encased in concrete. The soil contamination looks like historical spill, not new release. The excavation is extended down to 12 feet, no groundwater was encountered. The excavation is still open and covered with plastic sheeting. The backfill will be pending on the other excavation and potential development. No new tanks to be installed. There is a potential that the site to be developed, no certain schedule yet. It is still in conceptual phase. In order to develop, they need to apply to OER to remove the e-designation for zoning change from commercial to residential. There is a closed old spill 07-09362. The latest report show that MW-8 was detected with 1,847 ug/L BTEX. They are proceeding to remove the other (2) 4,000-gallon USTs. Today they may uncover the concrete and by Monday they may yank the USTs out. A USTs Excavation report will be sent.
Tim Fisher Antea Group 914-495-9935 Discussed with Rick Lin and will

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

assign him the spill and will notify Kevin Hale. 03/22/19 - Site
reassigned to Randy Whitcher of SRC for to be included in the Getty
portfolio. - RJW"

Remarks:

"2 of 4 tanks removed clean up pending test results"

All Materials:

Site ID: 584254
Operable Unit ID: 1331921
Operable Unit: 01
Material ID: 2341143
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported